


LS-175E and MLS175E INSTRUCTIONS FOR LEAD SCREW REMOVAL



**For re-assembly
reverse procedure**

Visit us on the World Wide Web at <http://www.hypneumat.com>

Hypneumat Inc.
5900 West Franklin Drive
Franklin, WI 53132-9178
Phone: (414) 423-7400
Fax: (414) 423-7414