

# Multiple Spindle ADAPTATIONS

*Multiple Spindle Drill Heads can be easily adapted to:*

- Drill Presses
- Automatic Drill Units
- Tapping Machines
- Self-Feed Air Drills
- Special Machines
- Transfer Machines
- CNC Machining Centers with tool changers

## Typical Drilling Machine Spindle Configurations

